




Office Electrical Safety


Follow these tips to keep your workspace safe from electrical hazards.



Unusually warm outlets indicate unsafe wiring that needs inspection.



Never connect plugs that have broken or missing prongs.



Replace any frayed, cracked, or damaged cords immediately.



Avoid overloading power strips to minimize overheating.

